

Dear Customer,

September, 2019

Datasheet Correction: List of all pins of TPM3H Group(1)

This informs you that we found the following corrections should be made to the datasheets as shown below. If you have any questions or require any further information, please contact your local Toshiba representatives.

1. Products

TMPM3H6FWFG · TMPM3H6FUFG · TMPM3H6FSFG
TMPM3H6FWDFG · TMPM3H6FUDFG · TMPM3H6FSDFG

TMPM3H5FWFG · TMPM3H5FUFG · TMPM3H5FSFG
TMPM3H5FWDFG · TMPM3H5FUDFG · TMPM3H5FSDFG

2. Applicable Datasheet

TMPM3H Group(1) Datasheet Revision 4.0 or past

3. Corrections

The pin name and pin number are described at «Pin Assignment» «Power Supply pins» «List of All pins» in datasheet. We corrected «List of All pins» in datasheet as follows. The «Pin Assignment» and «Power Supply pins» are described correctly in datasheet.

[Error]

Appendix

List of All pins

Combination Function A to B: These are the
Combination Function 1 to 6: These are the

List of All pins(1)

M3H6 (LQFP100)	M3H6 (QFP100)	M3H5 (LQFP80)	M3H4 (LQFP64)	M3H3 (LQFP52)	M3H2 (LQFP48 VQFN48)	M3H1 (LQFP44)	M3H0 (LQFP32)	Port Name
1	3	-	-	-	-	-	-	PD3
2	4	1	1	1	1	1	-	PD2
3	5	2	2	2	2	2	1	PD1
4	6	3	3	3	3	3	2	PD0
5	7	4	4	4	4	4	3	AVDD5
6	8	5	5	5	5	5	4	AVSS
7	9	6	6	6	6	-	-	PG0
8	10	7	-	-	-	-	-	PG1
9	11	8	-	-	-	-	-	DVDD5C
10	12	9	-	-	-	-	-	DVSSC

[Correction]

Appendix

List of All pins

Combination Function A to B: These are the
Combination Function 1 to 6: These are the
The noise filters in the table do not include

List of All pins(1)

M3H6 (LQFP100)	M3H6 (QFP100)	M3H5 (LQFP80)	M3H4 (LQFP64)	M3H3 (LQFP52)	M3H2 (LQFP48 VQFN48)	M3H1 (LQFP44)	M3H0 (LQFP32)	Port Name
1	3	-	-	-	-	-	-	PD3
2	4	1	1	1	1	1	-	PD2
3	5	2	2	2	2	2	1	PD1
4	6	3	3	3	3	3	2	PD0
5	7	4	4	4	4	4	3	AVDD5
6	8	5	5	5	5	5	4	AVSS
7	9	6	6	6	6	-	-	PG0
8	10	7	-	-	-	-	-	PG1
9	11	8	-	-	-	-	-	DVSSC
10	12	9	-	-	-	-	-	DVDD5C